



Key Indicator - 7.1.3 Quality audits on environment and energy regularly undertaken by the Institution.

Metric No: 7.1.3 Quality audits on environment and energy regularly undertaken by the

Institution. The institutional environment and energy initiatives are confirmed through the following:

Index

Sr No	Name of Audit	Year of Audit	Page No
1	Energy Audit	2022-23	1

Certified documents from page no 1 to 1

NITIN
KRISHNARAO
CHOUDHARI

Digitally signed by
NITIN KRISHNARAO
CHOUDHARI
Date: 2023.11.01
16:03:21 +05'



Energy Audit Document 2022-23

Energy Audit Report: Priyadarshini Bhagwati College of Engineering, Nagpur: 22-23

ENGRESS SERVICES

Yashashree, 26, Nirmal Bag Society, Near Muktangan English School,
Parvati, Pune 411 009, Email: engress123@gmail.com
MEDA Registration No: ECN/2022-23/CR-43/1709
ISO: 9001-2015 Certified (Cert No: 23EQKC13),
ISO: 14001-2015 Certified (Cert No: 23EEKW20)

ENERGY AUDIT CERTIFICATE

Certificate No: ES/PBCOE/22-23/01

Date: 10/7/2023

This is to certify that we have conducted Energy Audit at Lokmanya Tilak Jankalyan Shikshan Sanstha's Priyadarshini Bhagwati College of Engineering, Harpur Nagar, Umred Road, Nagpur in the Year 22-23.

The College has adopted following Energy Efficient Practices:

- Usage of Energy Efficient LED Fittings
- Maximum usage of Day Lighting
- Installation of Roof Top Solar PV Plant of Capacity 84 kWp

We appreciate the support of Management, involvement of faculty members and students in the process of making the Campus Energy Efficient.

For Engress Services,

A Y Mehendale,
B E- Mechanical, M Tech, Energy
Certified Energy Auditor, EA-8192

